HONEYWELL INTERNATIONAL, INC.
CONSUMER PRODUCTS GROUP
SAFETY RECALL

FRAM RACING HP4 and HP8 OIL FILTERS – Manufactured from May 25, 2006 through September 14, 2007

Honeywell is recalling FRAM® Racing HP4 and HP8 oil Filters that were manufactured from May 25, 2006 through September 14, 2007. **The affected filters are marked with a date code A61451 through A72571 sequentially.** The date code and part number appear on the filter housing, as shown above. FRAM Racing HP4 and HP8 oil Filters not bearing a date code in this range are not affected by this recall.

The gasket of the oil filter becomes more pliable under high temperatures and pressures. This condition may cause inadequate sealing and loss of engine oil.

If you own the affected product, please return it to the retailer or installer from whom you purchased the filter for a refund.

QUESTIONS? CALL 1-800-890-2075 (option 1)

MONDAY THROUGH FRIDAY, 8:00 AM TO 4:45 PM, EST

SAFETY RECALL NOTICE
Voluntary Safety Recall Campaign 07E088
November 2, 2007

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Honeywell Consumer Products Group has decided that a defect which relates to motor vehicle safety exists in certain HP4 and HP8 oil filters manufactured and distributed by Honeywell under the FRAM Racing brand name. Honeywell is voluntarily recalling the affected product.

WHAT PRODUCTS ARE INVOLVED?

This recall involves FRAM Racing HP4 and HP8 oil filters that were manufactured from May 25, 2006 through September 14, 2007. These products were sold exclusively in the aftermarket.

Important Note: This recall does not involve all HP4 and HP8 filters. Rather, only products with date codes A61451 through A72571 sequentially marked on the oil filter housing are subject to this recall. A depiction of the product showing location of the date code is attached to this notice.

WHAT IS THE PROBLEM?

The gasket of the oil filter may become more pliable under high temperatures and pressures. This condition may cause inadequate sealing and loss of engine oil.

WHAT SHOULD YOU DO?

If you have purchased one of the subject oil filters through a retailer or installer, please contact your supplier for replacement instructions. Refunds are available upon return of the product to your supplier.

If you have any questions, please call FRAM Customer Service at 1-800-890-2075 (option 1). You may also contact the Administrator, National Highway Traffic Safety Administration, at 1200 New Jersey Avenue, SE, Washington, D.C. 20590; or call the toll-free Auto Safety Hotline at 1-888-327-4326 (TTY: 1-800-424-9153); or go to http://www.safercar.gov, if you are unable to obtain a remedy without charge within a reasonable time.

The part number (HP4) and the date code (eg. A63201) are found on the side of the oil filter.

The part number (HP8) and the date code (eg. A72561) are found on the side of the oil filter.

The UPC number (0910075146) and the part number (HP4) are found on the end of the carton.

The UPC number (0910001451) and the part number (HP8) are found on the end of the carton.

FRAM apologizes for any inconvenience this may cause, but is taking this action in the interest of your personal safety and satisfaction with our products. Thank you for your cooperation.